## Maryland Historical Trust State Historic Sites Inventory Form

Magi No 2104935204
DOE \_\_yes \_\_no

1. Nan	1e (indicate pr	eferred name)		
historic Mor	ling's Chance			
and/or common	Paul Rust Res	idence		
2. Loca	ation			
street & number	· Bloomfield Ro	ad		not for publication
city, town	Easton	X vicinity of	congressional district	lst District
state Ma	ryland	county	Talbot County	
3. Clas	sification			
Category  — district  X building(s)  — structure  — site  object	Ownership public both Public Acquisition in process being considered not applicable	Status _X_ occupied unoccupied work in progress Accessible _X_ yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park X private residence religious scientific transportation other:
4. Own	er of Prope	<b>'ty</b> (give names ar	nd mailing addresse	s of <u>all</u> owners)
name Mr.	and Mrs. Paul D	. Rust	•	
street & number	Route 5, Box	499	telephone no	).:
city, town Blo	omfield,	state	and zip code Mary	land 21601
5. Loca	ation of Lega			
courthouse, regi	stry of deeds, etc. Talb	ot County Courth	ouse	liber
street & number	Washington Stre	et		folio
city, town	Easton		state	Maryland
6. Repr	resentation	in Existing	Historical Surve	eys
title				
date pository for su	rvey records		federal state	e county local
city, town			state	

<b>7.</b>	Des	crip	tion

Survey No.T-493

Condition excellent	deteriorated	Check one unaltered	Check one X original site	
Xgood fair	ruins unexposed	X altered	moved date of move	

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

Morling's Chance is located at the south end of Bloomfield Road and on the north bank of Shipshead Creek, a tributary of the Tred Avon River, approximately 3 miles west of Easton.

The log house at Morling's Chance is a small one room plan building that has been reincorporated into a larger "mail order" dwelling house built about 1922.

The house measures  $13\frac{1}{2}$  feet deep and  $15\frac{1}{2}$  feet long, and presumably originally had a pitched gable roof. The house is oriented on an east-west axis with the south facade facing the water. A brick exterior chimney on the west gable wall serves a single fireplace on the first floor.

The house is constructed of hewn and pit sawn log planks joined at the corners with dovetail notching. The log walls are stabilized with wood pins driven vertically into the top and bottom faces of adjoining logs. The west gable wall was evidently also reinforced with intermediate posts flanking the chimney opening, as suggested by a series of wood pegs in the face of each log. The log walls were chinked with pieces, of riven stock and the spaces between the logs were covered originally (or at an early date) by riven clapboards secured with wrought mails. The exterior walls show traces of whitewash, which also may be seen on the one early clapboard that has surrived. In the 19th century the house was sheathed with heavy vertical exterior siding nailed with machine-made nails and covered with whitewash. This siding was later covered by several successive layers of weatherboard siding. .greaper its 987

Today, the log walls, the gable chimney, and the framing and flooring for the loft survive; while the first story flooring and the entire roof are gone. The lower logs on at least two walls appear to be early replacements, as the upper logs are oak, while the lower logs are pine. On the north facade wall the lower logs also have a distinctively different appearance due in part to the pattern of saw strokes.

When the house was recently renovated and the walls exposed, it became apparent that the fenestration pattern had undergone several changes. Before the renovation,

## 7.1 DESCRIPTION

there were single windows in the center of the north and south facades, an exterior door to the north of the gable chimney, and an interior door in the center of the east gable wall, opening into the 20th century kitchen. When the log walls were exposed, it became clear that the window in the north facade replaced an original door, and it seems likely that the south window was also originally a door.

The interior consists of a single room with an exposed hewn joist ceiling covered with numerous coats of whitewash. The ghost of a steep ladder-stair is visible in the southwest corner of the room, and the ghost of a corner cupboard may be seen on the ceiling in the northeast corner.

Period prehistori 1400–149 1500–159 1600–169 1700–179 1800–189 1900–	9 <u>X</u> archeology-historic 9 <u>agriculture</u> 9 X architecture 9 <u>art</u>		law literature military music at philosophy politics/government	religion science sculpture social/ humanitarian theater transportation other (specify)
Specific date	es	Builder/Architect	:	
Арр	olicable Criteria:A and/or olicable Exception:/	A _B _C _D	EFG local	

Survey No. T-493

8. Significance

Prepare both a summary paragraph of significance and a general statement of history and support.

This small log house is located on a tract of land known as Morling's Chance, which can be traced back at least as early as 1740, when Jacob Morling conveyed the property to Samuel Chamberlaine. Jacob is described as the "heir apparent" of Jacob Morling "who left Talbott County .... about the year .... One Thousand seven hundred and Twenty".

The house is typical of a small dwelling house or detached kitchen of the 18th or early 19th century, and if used as a dwelling may have been occupied by a tenant farmer, overseer, indentured servant or slave. Although the house has been extensively altered, the dovetailed log walls, brick exterior chimney, exposed joist ceiling and flooring survive as well as evidence of riven clapboard siding, a steep ladder-stair, and a corner cupboard. Dating evidence is extremely limited but wrought nails used to secure the clapboard siding suggest a date no later than 1815, and it seems likely that the building dates to the last quarter of the 18th century or the first decade of the 19th century.

The early log house has been incorporated into the wing of a small frame house constructed in 1922. According to the present owner, this 20th century dwelling was a mail order house, but the company is not known.

## 9. Major Bibliographical References

Survey	No.	T-493	
--------	-----	-------	--

10. G	eographica	al Data				
Acreage of no	ominated property		-	Quadr	angle scale	
-	ces do NOT comple	te UTM referen	ces		ara . 1	
^	asting Northi		BZo	ne Easting	Northing	
c L			D			
E			F [			
G L			н			
Verbal bour	ndary description and	justification				
		and the second second			* 44	
List all stat	es and counties for p	roperties overlap	ping state o	or county boundar	ies	
state		code	county	7.	code	
state	· · · · · · · · · · · · · · · · · · ·	code	county		code	
11. F	orm Prepar	ed By		<b>**</b>		
name/title	Orlando Ri	dout V				
organization	Maryland H	istorical Ti	ust	date		
street & numi	oer 21 State C	ircle	په لډ	telephone 2	69-2438	
city or town	Annapolis			state Mary	land""	
Fi	•	MD-9; Recor	ded Sept	tember 14, 1	983	
	The Maryland His an Act of the Ma Code of Maryland	ryland Legisla	ture to b	e found in the 81 KA, 1974 su	Annotated pplement.	
				an dranet	វឌ្ឍ១១៩១៥	
o :	The survey and i record purposes individual prope	only and do no	eing prep t constit	ared for infor ute any infrin	mation and gement of	
	Sh	ryland Histori aw House State Circle	cal Trust			

Annapolis, Maryland 21401

(301) 269-2438

